Approved For Release 2006/10/12 CIA-RDP78B03817A000700020033-0 CONFIDENTIAL

PRIORITY
OUT 62683

P 220420Z JUL 67
FM NPIC WASH DC
TO AIG NINE SEVEN SIX
RUEPJS/DIA PRODCEN
RUEPJS/NIC
BT
C O N F I D F N T I A

1967 JUL 22 04 42 Z

CONFIDENTIAL. CITE NPIC 1343.

CPIR:NPIC SER: F00408 UEYT MSN:0085W1 30JUN67H

DAY PHOTO. CAMERA ON/OFF TIMES UNK. REF A. NPIC MSG 8865, DTG 2422082

OCT 66. REF B. NPIC MSG 9018, DTG 092323Z, NOV 66. AMS SERIES

L7014, SHEET 6051-I, 1ST ED. PACOM NORTH VIETNAM CPFL ICOD 5JUN67.

PART I. SIGNIFICANT PHOTO INTERPRETATIONS

B. NEW TARGETS AND SIGNIFICANT CHANGES

File SEC BR TDS CSD !PD PD FSD PSO-ICB TID IAD PAG DIAXX-4 SPAD -NSA-LO DIA-AP Advance gopy

DISTRIBUTION

Office

Action

Ky No.

RMK:EARLY STAGE RECONSTRUCTION WORK IS OBSERVED AT THE SITE OF

THE DESTROYED VIET TRI RAILROAD AND HIGHWAY BRIDGE OVER THE

RIVIERE CLAIRE AT 21-17-50N 105-26-55E. THREE LARGE CABLE

ANCHORAGE EXCAVATIONS ARE UNDER CONSTRUCTION ON EACH OF THE 2

APPROACHES. APPROXIMATELY 50 COILS OF CABLE ARE LOCATED IN THE

VICINITY OF THE SE APPROACH. THE ABUTMENTS OF THE ORIGINAL BRIDGE

ARE APPROXIMATELY 960 FT APART. ONE PIER, 1 SPAN, AND BOTH

ABUTMENTS APPEAR UNDAMAGED. THE REMAINING 3 SPANS ARE DESTROYED.

THERE IS NO EVIDENCE OF PIER RECONSTRUCTION.

25X1

ITM02:RR FERRY CROSSINGS VIET TRI SGM:6A2C CTY:VN 211750N1052640E RMK:THE PREVIOUSLY REPORTED (REF A) RAIL FERRY SLIPS SW OF THE DESTROYED VIET TRI RAILROAD AND HIGHWAY BRIDGE AT UTM WJ462550

<u>Declassification Review by NGA</u>

CONFIDENTIAL

GROUP 1
Excluded from automatic downgrading with declassification

- 2 -

AND WJ464549 ARE NOW UNSERVICEABLE AND IN DISUSE. THE PREVIOUSLY REPORTED (REF B) HIGH WATER RAIL FERRY SLIPS AT WJ461548 AND WJ459549 ARE SERVICEABLE. TWO LOW WATER RAIL FERRY SLIPS AT WJ458549 AND WJ461548 ARE PRESENTLY INUNDATED. SIXTEEN PIECES OF ROLLING STOCK ARE LOCATED ON THE SE APPROACH.

25X1

ITMØ3:VIET TRI RR YARD

SGM:6A12R CTY:VN 211800N1052600E

RMK:THE 5-TRACK VIET TRI RAILROAD YARD HAS BEEN SUBJECTED TO
HEAVY AIR STRIKES; HOWEVER, 2 THROUGH TRACKS HAVE BEEN REPAIRED
AND ARE SERVICEABLE. EQUIPMENT IN THE YARD INCLUDES 15 SERVICEABLE
AND 10 DAMAGED/DESTROYED PIECES OF ROLLING STOCK.

25X1

PART II OTHER PHOTO INTERPRETATIONS - NOME

GP-1

CONFIDENTIAL

-END OF MESSAGE-

MS/C NOTE: ALSO 25X1